



FIG. 1


**FIG. 2A**




**FIG. 2B**



**FIG. 2C**





**FIG. 3**




FIG. 4A




FIG. 4B





FIG. 4C

FIG. 5A



**FIG. 5B**




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11






FIG. 12




FIG. 13





FIG. 14






FIG. 16




FIG. 1 is a perspective view of a vehicle 210. The vehicle includes a rear cargo door 211 and a lift system 250. The lift system 250 is mounted to the rear of the vehicle. It includes a base 220, a vertical support 222, and a telescopic arm 255. The telescopic arm 255 has sections 233, 239, and 262, and a handle 264. The vehicle 210 has wheels 213 and 215.






FIG. 18



[illegible]




Fig. 20




Fig. 21






Fig. 22

Fig 23A




Fig. 23B





Fig. 23.C







Fig. 24

Fig. 25A



↑  
302

Fig. 25C





Fig. 25B



↑  
302

Fig. 25D

